

Equipping the Nation's Drink Producers


Label Printing Instructions for the VL1 Labeller Stock Code: 98396

## IMPORTANT INFORMATION

The information contained in these pages must be given to your label printers **before** labels are printed.


[VERSION CJB FEB 2018]

## SIZES AND POSITION OF THE LABELS ON ROUND BOTTLE FOR THE MACHINE



 ATTENTION: for greater heights, keeping the upper edge of the label unalterated, move the paper support disks.

> Vigo Ltd, Dunkeswell, Devon, EX14 4LF England Sales - 01404 892100 sales@vigoltd.com General - 01404 890262 info@vigoltd.com www.vigoltd.com Registered in England and Wales No. 3607580




Vigo Ltd, Dunkeswell, Devon, EX14 4LF England Sales - 01404 892100 sales@vigoltd.com General - 01404 890262 info@vigoltd.com www.vigoltd.com

Registered in England and Wales No. 3607580

## Direction of paper winding


Front and back labels must be wound as shown in Fig. A below (Outside wound right hand edge leading).

In each case the core diameter should be 76mm and the outside diameter of the label reel should be less than 270mm.




Cylindrical containers

If the front and back labels are on the same reel, the distance between the bottom of the label and the bottom of the backup paper must not exceed 18 mm (fig. C below).



Vigo Ltd, Dunkeswell, Devon, EX14 4LF England Sales - 01404 892100 sales@vigoltd.com General - 01404 890262 info@vigoltd.com www.vigoltd.com Registered in England and Wates No. 3607580



Vigo Ltd, Dunkeswell, Devon, EX14 4LF England Sales - 01404 892100 sales@vigoltd.com General - 01404 890262 info@vigoltd.com www.vigoltd.com Registered in England and Wales No. 3607580

## DETACHMENT OF THE LABEL FROM THE BACKING ALONG THE PAPER ROUTE.

IF THE LABEL IS MADE FROM PARTICULARLY STIFF OR HEAVY PAPER, AND THE SILICON BACKING DOES NOT HOLD IT SUFFICIENTLY, IT COULD COME UNSTUCK (SEE THE DRAWING).





FIG.1 - POSSIBLE INCONVENENCE



TO AVOID THIS INCONVENIENCE A \$\$60 ROLLER WITH CENTRAL SUPPORT BEARINGS SHOULD BE PUT AT THE CRITICAL POINTS OF THE PAPER ROUTE. THE LABEL DOES NOT USUALLY COME UNSTUCK FROM THE PAPER BACKING ON A ROLLER WHIT THIS DIAMETER.





FIG.2 - SOLUTION WITH \$60 ROLLERS



Vigo Ltd, Dunkeswell, Devon, EX14 4LF England Sales - 01404 892100 sales@vigoltd.com General - 01404 890262 info@vigoltd.com www.vigoltd.com Registered in England and Wales No. 3607580